


NYS BUILDING-STRUCTURE INVENTORY FORM
Amendment Sheet, p. 1
1998

518 First Street, SCTM: 004-03-6
Carrington, Harcourt A.
Kerr, Bette

12. Photograph, 1998



17. This house is located in the historic district.

18. This 2 ½ story house has been well maintained and all of its notable features have been well preserved. The house still has its old tin roof. The side gables have partially hipped roofs. An open front porch with square support posts and a shingled rail wraps around the south side of the house where it meets with a glass enclosed entryway. Another front door is located on the south end of the porch. The front porch is accessible from the south side only. The double hung windows in the front second story are capped and pedimented. The house has the same 2/2 windows throughout, and two decorative windows on the south side: an oval window with beveled glass and square stained glass window. There is a one story bay window off the center of the south side. A glass enclosed porch extends off the rear south side. A blue stone driveway is located on the south front side of the house; a chainlink fence divides front and back yard on that side. A wood deck has been built off the rear of the house. An old garage with a shed attachment can be found in the rear southeast corner of the property.